User:

Wednesday, 4/19/2006 8:14:15 AM

Kim Johnston

## **Process Sheet**

**Drawing Name** 

Part Number

**Drawing Number** 

Project Number

**Drawing Revision** 

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 26721A

**Estimate Number** 

: 10206

P.O. Number

Prsht Rev.

First Issue

Alla:

This Issue

: 4/19/2006

: NC

: 26720A **Previous Run** 

: N/A

S.O. No. : NA

: LARGE FAB ASS

Material **Due Date**  : N/A : 5/5/2006

: N/A

: B

: D2989041

D2989 REV B

: BASKET LID ASSEMBLY

Qty: 1 Um:

SC-10-90

Each

Checked & Approved By

Comment

Written By

: Est Rev:

05-11-03

**Additional Product** 

- 14 Job.Number:

Seq. #:

Machine Or Operation:

Description: Basket Hoop

D31663 1.0

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

3ed Pick:

Comment: Qty.:

Qty.(1) D3166-3

Batch: 626383

Mounting Bracket

2.0000 Each(s)/Unit Comment: .Qty.:

Total:

2.0000 Each(s)

Pick:

Qty Part number

Description Batch

2 D2581



Mounting Brackets 53630



3.0

D23273

Comment: Qty.: 12.0000 Each(s)/Unit

Total:

2.0000 Each(s)

Pick:

Qty Part number

Description Batch

2 D2327-3

Bushing

hasba

4.0

D2506

Placard

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

Pick:

Comment: Qty.:

Qty Part number

Description Batch

1 D2506

Label Plate 1026031

OF-04-95

Page:1

Form: rprocess

# **Dart Aerospace Ltd**

Du /	. oopaoo									
W/O:			W	ORK ORDER C	HANGES	· · · · · · · · · · · · · · · · · · ·			<u> </u>	
DATE	STEP	PRO	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								<u> </u>		1
	-									
Part No		PAR #:	Fault Cate	gory:	N	CR: Yes	No <b>DQ</b>	A:	Date: _	
							C Closed: Date:			
NCR:		V	VORK ORD	ER NON-CON	ORMANO	E (NCR	)	,		
DATE	OTED	Description of NC	Corrective Action Section B				Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Desc Chief En	ription	Sign & Date		on C	Chief Eng	QC Inspector
			••					!		
		····							<u>.</u>	
· ,										
		•			·		. •			
			1							1

NOTE: Date & initial all entries

Wednesday, 4/19/2006 8:14:15 AM Date: User: Kim Johnston **Process Sheet Drawing Name: BASKET LID ASSEMBLY** Customer: CU-DAR001 Dart Helicopters Services Part Number: D2989041 Job Number: 26721A Job Number: Description: Seq. #: **Machine Or Operation:** Expanded Metal Flat Stai M304EX07516F 5.0 Comment: Qty.: 15.0000 sf(s)/Unit Total: 15.0000 sf(s) Pick: Qty Part number Description Batch D HIDO13. 06-04-02 **Expanded Metal** 15sf M304EX0.75-16F 304 SQ Tube.75x.75x.065W 6.0 M304TS0750W065 31.7709 f(s) H100748 (192") Comment: Qty.: 31.7709 f(s)/Unit Total: 3/4" x 3/4" x 0.063" wall 304/316 SStubing. Batch: 4100704 M100025 (623) LARGE FAB 1 Comment: LARGE FABRICATION RESOURCE 1 1-Cut (4) D2236-1 From D3166-3 As Per Dwg D2989 2-Drill holes in tubing as D2989-041 per Dwg D2989 3-Deburr and remove all markings on material 4-Weld as per Dwg D2989 and D2989-041 Assembly using Welding Table and corner Jig. Deburr as Note: Expanded metal "diamonds" must run lengthwise. Eg 2.0" along length of lid 5-Drill Ø0.257" hole as D2989-041 per Dwg D2989Identify as D2989-041 DDIMENSIONAL & WELDING INSPECTION 8.0 QC9/6 Comment: DDIMENSIONAL & WELDING INSPECTION 9.0 POWDER COATING POWDER COATING Comment: POWDER COATING 1-Powder Coat White (Ref. 4.3.5.2) D2989-041 as per QSI 005 4.3 & Dwg D2989 @ .... 2-Wing walk D2989-041 as per Dwg D2989 and QSI 005 4.4 Spray Paint Black: M 19640 aim 06-08-10 Wing Walk: # M 1006 52

Page\_

Dart Aerospace Ltd							
W/O:		WORK ORDER	CHANGES				
DATE STEP		PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	• .	PAR #: Fault Category:	NCR: Ye	s No DQ	A: 😂	Date: <u></u>	Xd05/16
			QA:	N/C Close	d:	_ Date: _	
		WORK ORDER NON CO	NEODMANOE (NO	\D\			

	WORK ORDER NON-CONFORMANCE (NCR)								
	Description of NC		Corrective Action Section B						
STEP	Section A	Initial Chief Eng	Action Description \ Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector		
			•						
	STEP	STED Description of NC	STEP Description of NC Section A Initial	STEP Description of NC Section A Initial Action Description	STEP Description of NC Section A Initial Action Description Sign &	STEP Description of NC Section A Section B Initial Action Description Section C Section C	STEP Description of NC Section A Section B Initial Action Description Sign & Section C		

NOTE: Date & initial all entries

Date:

Wednesday, 4/19/2006 8:14:15 AM

User:

Kim Johnston

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

**Drawing Name: BASKET LID ASSEMBLY** 

Job Number: 26721A

Part Number: D2989041

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

10.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION

06:05:11

Comment: Inspect Powder Coat and Wing Walk 11.0

DC

DOCUMENT CONTROL

Comment: DOCUMENT CONTROL

Inspection Level 21

Job Completion



1 9 06/05 W Dlew 5.16

# **Dart Aerospace Ltd**

Dail Ac	OSPACE								
W/O:			WC	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	_ Date: _	
					QA: N/	C Close	d:	_ Date: _	
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NCR)	)			
		Description of NC	Corrective Action Se		on B	Verific	eation	Ammerial	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Approval Chief Eng	QC Inspector
							;		

NOTE: Date & initial all entries



DESIGN DRAWN BY DS PH		1	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECK	CHECKED _ APPROVED 41		DRAWING NO. REY	V. B
	At	THE SHE	D2989 SHEET 1 0	F 3
DATE			TITLE SO	ALE
05.0	6.07		BASKET LID ASSEMBLY	NTS
Α		00.10.27	NEW ISSUE	
В		05.06.07	ADD SHIM UNDER HINGES, UPDATE LID DIMENSIONS	

RELEASED 05.08.19

#### **PARTS LIST:**

Qty -041	Qty -043	Part Number	Description
Х		D2989-041	BASKET LID ASSEMBLY (OUTSIDE)
	X	D2989-043	BASKET LID ASSEMBLY (INSIDE)
	1	D2989-1	STRUT
	1	D2989-1 D2989-2	STRUT
	1	D2989-3	STRUT
	1	D2989-3 D2989-4	STRUT
	2	D2989-4 D2989-5	STRUT
	2	D2989-7	STRUT
1		D2989-9	STRUT
1		D2989-10	STRUT
1		D2989-11	STRUT
1		D2989-12	STRUT
2		D2989-13	STRUT
2	<u> </u>	D2989-15	STRUT
		D2000 10	
2	<u> </u>	D2327-3	SPACER BUSHING
1		D2506	LABEL PLATE
2	2	D2989-17	STRUT (96.00" LONG)
2		D2989-19	STRUT (31.19" LONG)
1		D2512-7	STRUT
2		D2581	MOUNTING BRACKET
	2	D3182-1	HINGE
	2	D3442-3	SHIM

### NOTES:

1) FRAME MATERIAL: AISI 304/316 SS, 3/4 x 3/4 x 0.060 WALL SQUARE TUBING D2989-3/4/5/11/12/13 CAN BE MADE FROM D2236

2) MESH MATERIAL: 3/4-16F EXPANDED SS (REF DART SPEC M304EX0.75-16F)

3) WELD PER DART QSI 004

4) FINISH: POWDER COAT WHITE (REF. 4.3.5.2) PER DART QSI 005 4.3.

BLACK ANTI-SKID PAINT AS INDICATED PER DART QSI 005 4.3.

INSIDE SURFACE BLACK PRIOR TO APPLYING ANTI-SKID.

5) ALL DIMENSIONS ARE IN INCHES

5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

SHOP COPY RETURN TO ENGINEERING

NO. 36727

Copyright © 2000 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



